



Summary for Notification of Exceedance

Ref No.	Date	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up Action
-	-	-	-	-	-	-	-

Ref. No.	Date	Time	Location	Construction Noise Level	Parameter	Action Level	Limit Level	Follow-up action
X_N001	23-Oct-21	08:52	NMS1 - 1 Tung Wan Tau Road	77.7	Leq(30-min)	when one documented complaint was received.	75	<ul style="list-style-type: none">Repeated measurement (78.9) to confirm exceedanceInvestigate cause by abnormal engine vibration from pre-drillingContractor repair abnormal engine vibrationNo further exceedance (74.0) after repair